



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Date: December 17, 2008

Reviewed: 28

Mine Name: Henefer Red Clay	Permit Number: M/043/0014
Operator Name: Interpace Industries, inc.	Inspection Date: 12/04/2008
Inspector(s): Brett Gregory for Leslie Heppler	Time: 3:00 pm
Other Participants: None	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$63,300

Permit fee: Current.

Purpose of Inspection: Routine annual inspection.

Inspection Summary:

- 1) The bond is past its' renewal date of 08/06/2008, bond needs to be escalated.
- 6) Operator indicated by phone call to Lynn Kunzler, that had mined all clay and would begin reclamation of the site as soon as stockpiled materials and gravel is removed. (see photographs).
- 7) The disturbed areas of ground have not been contoured to meet specifications acceptable for reclamation standards and will need to be re-graded.

Photos attached

Conclusions and Recommendations: Operator needs to commence reclamation in the near future. DOGM will continue to monitor the site.

Inspector's Signature

BG:vs

cc: (OPERATOR)

O:\M043-Summit\M0430014-Heneferredclay\Inspections\insp-12042008.doc



Tumbleweeds gathering inside the pit.



Gravel piles being removed by the county.



Filtered gravel.



Filtered gravel.



Areas to be contoured.



Areas to be contoured.



Areas to be contoured.



Areas to be contoured.